


PERFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING
(PART - I)

(To be filled by the head of the School/Institute)


1. Name Of School **DAWA RINJUE SCHOOL**
2. Location **LALDHANG, VIKASNAGAR, DEHRADUN**
3. Plot Area **10,100 sqmt.**
4. Plinth Area **744 sqmt.**
5. Number of Storey **2**
6. Area of Constructed part of the building
7. If the building is constructed under the Supervision of Qualified Engineer, the following details may be given :-
- a) Name of Engineer with Qualification **RK Nautiyal , M Tech**
- b) Address of Engineer **Phase II Vasant Vihar Dehradun**
- c) If Structural Drawing used in construction. If available? **Yes**
- d) Name and Address of Architect with Qualification **Pragati Consultant
4/10 Rajpur Road D.Dun**
8. Whether the building has constructed for the purpose of:
- a) School **School**
- b) Residential Purpose and use of School
9. Material used for Roofs **RCC Slab**
- a) RCC Slab
- b) RS Joists & Battons
- c) Wooden Joists & Bottom
10. Material Used for Walls **Cement Mortar**
- a) Mud Mortar
- b) Cement Mortar
- c) Lime Mortar
11. Flooring **Terrace**
- a) Conglomerate
- b) Terrace
- c) Brick Paving
12. A detailed drawing indicating the doors along with windows and location fitting and windows attached
13. For Fire Safety
- a) Whether the width of staircase is 1.5 mtr **Yes**
- b) Whether portable fire extinguisher exists **Yes**
- c) Whether School Building is free from inflammable & Toxic material. **Yes**
- d) Whether cooking food is done at a safe place **Yes**
- e) Whether ant Thatch or combustibile material has been used **No**


President
D.R. School Society
Dehradun Road, Herbertpur
Distt. D.Dun (U.K.)



14. Requirement for Fire Protection Arrangements under NB-Part IV
(For Building height less than 15 meter)

- | | |
|---|-----|
| a) Whether Hose Reel Provided | Yes |
| b) Whether dome cover provided | Yes |
| c) Whether Automatic Sprinkler Provided | No |
| d) Whether underground Static water storage tank of Capacity 50000L (if covered area exceeds 1500 Sq. Mt.) | |
| e) Whether overhead tank of capacity 10000L exists | Yes |
| f) Whether one electric and one diesel pump of 3Kg/cc Pressure of Capacity 1620 LPM, one electric pump of Capacity 190 LPM exist near underground static tank | No |



Signature of the Head of School/Institute
Dehra Dun Road,
Herbertpur, Dehra Dun


PART-II

(To be filled by the PWD department)

- a) I have visited the above mentioned school on dated 14/06/19 and have visually inspected it from all angles of safety and find it fit for normal use as school building.
- b) In case any addition/alteration or expansion and modifications to this building is to be carried out, the same be carried out under the supervision of qualified Engineer and this certificate may be re-obtained after completion from the undersigned.
- c) In case the building safety is affected by flood or if there is settlement of walls/foundation or sagging in roofs etc immediate inspection of the undersigned be arranged to check the stability of the building.
- d) This building can be safely occupied for normal use up to (Indicate which it can be used) one year




President
D.R. School Society
Dehradun Road, Herbertpur
Distt. D. Dun (U.K.)


14/6/2019
सहायक अभियन्ता
रा० मा० र. - ल० नि० वि०
डोईवाला, देहरादून